
0S20 0S21

MIYOTA




Battery consumption could be minimum by pulling out the stem

Balance Minute 0.40 Weight Chrono Second 0.11 <µN.m> Small 0.02

Featured by Shock Detection

Clearance

Clearance changes subject to the glass, case structure, and the length of the hand.



Original Package


500pcs

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec















Chronograph Minute 24 Hour





Reset the chronograph

Setting the Time

Set CHRONOGRAPH hands to reset

Push A to reset the hands position to the ZERO position, And continue to push A to put them forward